

# Oil Field Environmental Incident Summary

**Incident:** 20130221114012

**Date/Time of Notice:** 02/21/2013 11:02

**Responsible Party:** MBI

**Well Operator:** MARATHON OIL COMPANY

**Well Name:** DEEP CREEK 21-13TFH

**Field Name:** LOST BRIDGE

**Well File #:** 21840

**Date Incident:** 2/20/2013

**Time Incident:** 17:00

**Facility ID Number:**

**County:** DUNN

**Twp:** 148

**Rng:** 96

**Sec:** 13

**Qtr:** NW NW

**Location Description:** Spill occurred 1.5 miles off of location when truck left the road due to increased speed for condition of road. The truck came to a rest on its side on the left hand side of the ditch as the truck was headed NE.

**Submitted By:** Tonya Woolery

**Received By:**

**Contact Person:** Tonya Woolery  
3172 HWY 22 N  
DICKINSON, ND 58601

**General Land Use:** Other - Described Above

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels		
Brine	15	gallons	15	gallons		
Other	0	barrels	0	barrels	15	gallons

**Description of Other Released Contaminant:**

Truck rollover

**Inspected:**

**Written Report Received:** 10/9/2015

**Clean Up Concluded:** 2/21/2013

**Risk Evaluation:**

No immediate hazardous conditions or human health risk.

**Areal Extent:**

**Potential Environmental Impacts:**

Completions safety personnel responded to the spill. They brought a spill trailer and took preventive measures to contain the spill until the produced water could be off-loaded.

**Action Taken or Planned:**

All produced water that was inside the trailer was off-loaded into 2 vac trucks and sent to an MBI disposal well. The 15 gallons that contacted the ground was from the off-loading process. Affected material was cleaned up and removed by an MBI approved contract company.

**Wastes Disposal Location:** Recovered affected soil/snow was cleaned up by MBI and disposed of according to their company guidelines.

**Agencies Involved:** Local Law Enforcement

**Updates**

---

**Date:** 2/25/2013    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release occurred along a road. Follow-up is necessary. Determine what MBI company policies are for waste disposal.

---

**Date:** 3/1/2013    **Status:** Inspection

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On location 12:13 this date. Located apparent incident location. 49deg 39.132min, - 102deg50.168min. Vehicle missed corner. From indications, 15 gal volume is reasonable. Likely this is an overestimate based on small leakage during the transloading to another truck. Saw no other locations along this road that have any indication of vehicle leaving the road.

---

**Date:** 10/1/2014    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

10/1/2014 at 14:02, on location at wellpad. Left wellpad and proceeded along road until reaching ~1.5 miles from wellpad. No visibly impacted/dead vegetation in left side (north/west) ditch for a few hundred feet along roadside.